

# H.O.P.E. Toward Homeownership Program Donated Properties Before, During & After





## Holly Circle, Forest Park, GA — Before






















# Holly Circle, Forest Park, GA — During







Workers remove shingles and prepare to repair holes in the existing roof. A complete new roof was installed.











Old cabinets, which were in disrepair, were removed, and the entire kitchen was gutted for a full rehabilitation, including energy-efficient appliances.




The house had beautiful hardwoods hidden under dirty, stained carpet. The bathroom, kitchen, roof, flooring, lights and electrical service were completely reworked.



A new ceramic tile floor is installed during kitchen renovation.

## Holly Circle, Forest Park, GA — After























#### 948 Alvision, Toledo OH — Before











This beautiful old home shows what can happen when rainwater and vandals find their way inside. Rotting wood on the roof decking and shingles that needed replacing allowed water in causing damage to the walls and ceilings. The house was stripped of cooper, windows were broken giving access to the house. The porch foundation needed work, and she needed new flooring, new paint and a revitalized basement. Fortunately, H.O.P.E. Through Divine Intervention recognizes potential.



The wrap is coming undone and wood rot was found on the roof decking. Wrap arounds for some windows were also a problem.




A leaky roof allowed water into the house damaging the ceiling and prompting mildew to develop.



Kitchen cabinets were missing doors and drawers. The stove hood was grimy, and no appliances remained in the house.

# 948 Alvision, Toledo OH — During








With the roof completed and repairs made to the walls and ceilings the painters work their magic. The newly replaced window restores light to the room. Existing flooring, which was in poor condition, has been removed and new flooring will be installed once painting is complete. Repairing and replacing the vandalized heating system is a major part of this rehab project.

# 5254 N. 53rd St., Milwaukee WI — Before





This traditional frame house looks small from the front, but inside there is a large room in the attic perfect for play. The basement (although a little damp prior to rehabilitation) has a laundry area and lots of space.



Lovely hardwoods and a spacious kitchen just need refinishing



An unruly overgrown backyard




Broken windows and wires out of place



A leaky basement with lots of potential

# North 53rd Street, Milwaukee WI — After



The pictures tell the story. A foreclosure in need of repairs meets a family in need of a home.


















# 1029 Bricker, Toledo OH — Before





A frame house with lots of promise, but a few issues with the basement, the electrical service, and the HVAC system offered plenty of promise, including an expansion in the attic. HTDI kept its mission alive by making the needed repairs and creating an affordable rental.














### 1029 Bricker, Toledo OH — After






The smiles on this mother and her sons' faces tell the story.

Once renovations on this home were completed, the family moved in to enjoy an updated kitchen, a renovated bathroom, fresh new carpet on the floors and bright new paint on the walls.

A lovely living room complete with a large picture window and a beautiful decorative front door will be the site of many family nights to come.

The H.O.P.E. Toward Homeownership program is committed to meeting people where they are with housing opportunities that work for them.







A newly renovated kitchen ready for home- cooked meals.



Splish, splash mom can take relaxing baths in her newly renovated bathroom.



HTDI attempts to maintain unique features of homes such as this arched doorway.